

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 16011635	Report to All Drivers: NO	At Intersection with: "N/A"
Date of Acc: 11/06/16	Legal Intervention: NO	Div HWay Trvl Dir: "N/A"
Time of Acc: 20:20 Hrs.	Private Property: NO	Distance 1: "N/A"
Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF	County: PLYMOUTH - 75	Direction 1: "N/A"
Officer: DEPUTY JARY VERMEYS	Acc Loc City:	Distance 2: "N/A"
Badge #: 75-7	Acc Dir From City: "N/A"	Direction 2: "N/A"
Report Date: 11/06/2016	Closest City: "N/A"	X-Coordinate: 00229280
Officer Notified: 20:34 Hrs.	Miles From City: "N/A"	Y-Coordinate: 04722137
Officer Arrived: 20:48 Hrs.	Road,Street,HWay: "N/A"	Location Literal: US 75 MEASURING 1139 FEET
Scene Investigated: NO	Definable Locatlon: "N/A"	Description: NORTH FROM US 75 AND HARNESS RD
	Milepost Number: "N/A"	

Unit 001

Driver Name - Last: STROUTH	Bus Use:	Transported to:
First: NICHOLE		
Middle: JOANN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SHELDON		
State: IA	Traffic Controls:	Special Veh Func:
Zip: 51201-0000		
Suffix:	Point of Init Impact:	Emergency Status:
Gender: Female	Most Damaged Area:	Cont. Circum., Drvr:
Age: 33	Undrird/Ovrrld:	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage:	
License Class: C	First Event:	
License Endorsmnt: NONE		
License Restrictions: B	Second Event:	
Speed Limit:		
Seating Position:	Third Event:	
Driver Condition:	Fourth Event:	
Alcohol Test Given: NO		
Drug Test Given: 1 - NONE	Most Harmful Event:	
Total Occupants: 1	Abg Switch Stat:	
Vehicle Year: 2013	Abg Deploy:	
Vehicle Make: VOLKSWAGON - VOLK		
Vehicle Model: JET	Trapped:	
Vehicle Style: SD	Ejection:	
Vehicle Color: GRAY - GRY	Ejection Path:	
Vehicle Config: 01 - PASSENGER CAR	Occpnt Protect:	
Vehicle Defect:	Injury Status:	
Vehicle Action:		
Tow: 1 - DRIVEN AWAY	Source of Trans: 01 - NOT TRANSPORTED	
Tow #:	Died at Scene: 01 - NOT APPLICABLE	
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
Surface Conditions:	Type of Road Junc/Feat:
Workzone Related:	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: 31 - ANIMAL
Workers Present:	

Narrative

VEHICLE 1 WAS TRAVELING NORTH ON HWY 75. A DEER CAME FROM THE MEDIAN AND RAN INTO THE DRIVER'S FENDER CAUSING DAMAGE. VEHICLE WAS DRIVEABLE FROM THE SCENE.



not to scale

