

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	18-007944	Report to All Drivers:		At Intersection with:	
Date of Acc:	07/01/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	10:15 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	
Officer:	DEPUTY MATT M STRUVE	Acc Loc City:		Distance 2:	
Badge #:	75-9	Acc Dir From City:		Direction 2:	
Report Date:	07/01/2018	Closest City:		X-Coordinate:	00237615
Officer Notified:	22:23 Hrs.	Miles From City:		Y-Coordinate:	04741875
Officer Arrived:	22:38 Hrs.	Road, Street, HWay:		Location Literal:	US 75 MEASURING 6144 FEET
Scene Investigated:	NO	Definable Location:		Description:	NORTH FROM US 75/US 75 RAMP
		Milepost Number:			

Unit 001

Driver Name - Last:	VOGT	Bus Use:		Transported to:	
First:	SCOTT	Drv Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	RAYMOND	Traffic Controls:		Special Veh Func:	
City:	SIOUX CITY	Point of Init Impact:		Emergency Status:	
State:	IA	Most Damaged Area:		Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	51109-0000	Undrld/Ovrid:		Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$2,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:		Carrier City:	
Age:	54	First Event:		Carrier State:	
CDL:	NO	Second Event:		Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:		HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:		Abg Deploy:		Placard #:	
Seating Position:		Trapped:		HazMat Released?:	
Driver Condition:		Ejection:		Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:		GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:		Cit Chrg Code 1:	
Total Occupants:	4	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Year:	2014	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Make:	CHEVROLET - CHEV			Citation Charge 3:	
Vehicle Model:	IMP			Citation Charge 4:	
Vehicle Style:	4D				
Vehicle Color:	MAROON, BURGUNDY (PURPL				
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:					
Vehicle Action:					
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:					
Vision Obscured:					

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

Unit 1 was southbound on Highway 75 somewhere between MM118 and MM116 and struck a deer. Unit 1 continued to the Caseys in Merrill Iowa and called law enforcement to report the crash. Damage occurred to the front right side of the vehicle. The driver is also missing his front license plate that occurred during the crash.

