## INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: SO11000181 Legal Intervention: NO At Intersection with: "N/A" Date of Acc: 01/24/11 Private Property: NO Div HWay Tryl Dir: "N/A" Time of Acc: 05:30 Hrs. County: PLYMOUTH - 75 Distance 1: "N/A" Name of Agency: PLYMOUTH COUNTY SHERIFF'S Acc Loc City: Direction 1: "N/A" Acc Dir From City: "N/A" Distance 2: "N/A" Officer: LUBBEN, JIM Closest City: "N/A" Direction 2: "N/A" Badge #: 75-5 Miles From City: "N/A" X-Coordinate: 00249912 Report Date: 01/24/2011 Road, Street, HWay: "N/A" Y-Coordinate: 04724606 Officer Notified: 05:35 Hrs. Definable Location: "N/A" Location Literal Officer Arrived: 06:28 Hrs. Milepost Number: "N/A" Description:

C060 / C60 MEASURING 0.3 MILES EAST FROM K064 / OYENS AVE AND C060 / C60 AND OYENS AVE

Unit 001

Scene Investigated: YES

Driver Name - Last: MILLER Towing: YES Injury Status: 5 - UNINJURED First: DARIN Initial Tryl Dir. 4 - WEST Transported to: Middle: J Vision Obscured: 01 - NOT OBSCURED Transported by: Address: 403 HERBOLD AVE. Emergency Veh: 1 - NOT APPLICABLE **PIERSON** City: Traffic Controls: 01 - NO CONTROLS PRESENT Emergency Status: 3 - NOT APPLICABLE State: IΑ Cont. Circum., Drvr: 28 - NO IMPROPER ACTION Zip: 51048 Point of Init 02 - RIGHT FRONT Suffix: Impact: Carrier Name: Gender: MALE Most Damaged 09 - TOP Carrier Address: 42 Area: Age: Carrier City: License State: ĮΑ Undrrid/Ovrid: 1 - NONE Carrier State: License Class: Rpr/Rplc Cost: \$6,000.00 Carrier Zip: License Endorsmnt: NONE Ext of Damage: 5 - SEVERE, VEHICLE TOTALED Cargo Body Type: 01 - NOT APPLICABLE License Restrictions: 1, B First Event: 13 - OTHER NON-COLLISION Number of Axles: Speed Limit: HazMat Released? Seating Position: 01 - FRONT: LEFT SIDE / Second Event: 01 - RAN OFF ROAD, RIGHT GVWR: MOTORCYCLE DRIVER Placard #: Driver Condition: 1 - APPARENTLY NORMAL Third Event 11 - OVERTURN/ROLLOVER Cit Chrg Code 1: Alcohol Test Given: NO Citation Charge 1: Drug Test Given: NO Fourth Event Total Occupants: 01 Cit Chrg Code 2: Most Harmful 11 - OVERTURN/ROLLOVER Vehicle Year: 2001 Citation Charge 2: Event: Vehicle Make: **CHEVROLET - CHEV** Abg Switch Stat: 3 - NO ON/OFF SWITCH PRESENT **IMPALA** Vehicle Model: Cit Chrg Code 3: Abg Deploy: 5 - NOT DEPLOYED 4 DOOR Vehicle Style: Citation Charge 3: Trapped: 1 - NOT TRAPPED 01 - PASSENGER CAR Vehicle Config: Ejection: 1 - NOT EJECTED Cit Chrg Code 4: Ejection Path: 1 - NOT EJECTED/NOT Vehicle Defect: 01 - NONE Citation Charge 4: APPLICABLE Occpnt Protect: 2 - SHOULDER AND LAP BELT 01 - MOVEMENT ESSENTIALLY Vehicle Action:

## **Accident Environment**

STRAIGHT

First Harmful Event Loc: 1 - ON ROADWAY Roadway Characteristics Manner of Crash/Collision: 1 - NON-COLLISION Environment: 1 - NONE APPARENT **Light Conditions:** 5 - DARK, ROADWAY NOT LIGHTED Roadway: 07 - OBSTRUCTION IN ROADWAY Weather Conditions: 01 - CLEAR Type of Road Junc/Feat: 01 - NO SPECIAL FEATURE Surface Conditions: 4 - SNOW Workzone Related: NO Location: Type: First Harmful Evt of Crash: 13 - OTHER NON-COLLISION

USED

## Narrative

VEHICLE #1 WAS WESTBOUND ON C-60 WHEN HE ENTERED A LARGE SNOW DRIFT WHICH HAD COVERED THE WESTBOUND LANE OF TRAFFIC. THIS CAUSED A LOSS OF CONTROL. THE VEHICLE ENTERED THE NORTH DITCH WHICH WAS FULL OF SNOW, CAUSING THE VEHICLE TO ROLL ONE TIME AND END UP ON ITS TOP FACING SOUTH. THE DRIVER ADVISED HE WOULD CONTACT A TOWING COMPANY FOR REMOVAL AT A LATER TIME.

Workers Present:

Printed At: Plymouth County Sheriff's Off