

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	SO11002340	Legal Intervention:	NO	At Intersection with:	"N/A"
Date of Acc:	10/14/11	Private Property:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	06:00 Hrs.	County:	PLYMOUTH - 75	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	Acc Loc City:		Direction 1:	"N/A"
Officer:	LEUSINK, A	Acc Dir From City:	"N/A"	Distance 2:	"N/A"
Badge #:	75-9	Closest City:	"N/A"	Direction 2:	"N/A"
Report Date:	10/14/2011	Miles From City:	"N/A"	X-Coordinate:	00205623
Officer Notified:	06:00 Hrs.	Road, Street, HWay:	"N/A"	Y-Coordinate:	04734600
Officer Arrived:	06:35 Hrs.	Definable Location:	"N/A"	Location Literal:	240TH ST AND IOWA 0012 /
Scene Investigated:	YES	Milepost Number:	"N/A"	Description:	IOWA 12

Unit 001

Driver Name - Last:	PFEIL	Towing:	NO	Injury Status:	
First:	DANIEL	Initial Trvl Dir:		Transported to:	
Middle:	JAY	Vision Obscured:		Transported by:	
Address:	751 SOUTH ST	Traffic Controls:		Emergency Veh:	
City:	AKRON	Point of Init Impact:		Emergency Status:	
State:	IA	Most Damaged Area:		Cont. Circum., Drvr:	
Zip:	51001-0000	Undrrid/Ovrid:		Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$2,500.00	Carrier Address:	
Gender:	MALE	Ext of Damage:		Carrier City:	
Age:	40	First Event:		Carrier State:	
License State:	IA	Second Event:		Carrier Zip:	
License Class:	C	Third Event:		Cargo Body Type:	
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	NONE	Most Harmful Event:		HazMat Released?:	
Speed Limit:		Abg Switch Stat:		GVWR:	
Seating Position:		Abg Deploy:		Placard #:	
Driver Condition:		Trapped:		Cit Chrg Code 1:	
Alcohol Test Given:	NO	Ejection:		Citation Charge 1:	
Drug Test Given:	NO	Ejection Path:		Cit Chrg Code 2:	
Total Occupants:		Occpnt Protect:		Citation Charge 2:	
Vehicle Year:	2011			Cit Chrg Code 3:	
Vehicle Make:	CHEVROLET - CHEV			Citation Charge 3:	
Vehicle Model:	SLV			Cit Chrg Code 4:	
Vehicle Style:	PK			Citation Charge 4:	
Vehicle Config:					
Vehicle Defect:					
Vehicle Action:					

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	Workzone Related:
First Harmful Evt of Crash: 25 - ANIMAL	Location:
	Type:
	Workers Present:

Narrative

VEHICLE #1 WAS SOUTHBOUND ON HWY 12 AND STRUCK A DEER THAT CAME OUT OF THE WEST DITCH. DAMAGE WAS DONE TO THE FRONT PASSENGER SIDE OF THE VEHICLE AND THE PASSENGER SIDE OF THE VEHICLE. THE SIDE AIRBAGS WERE DEPLOYED.