

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: SO11001545	Legal Intervention: NO	At Intersection with: "N/A"
Date of Acc: 07/12/11	Private Property: NO	Div HWay Trvl Dir: "N/A"
Time of Acc: 11:05 Hrs.	County: PLYMOUTH - 75	Distance 1: "N/A"
Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF	Acc Loc City: "N/A"	Direction 1: "N/A"
Officer: LUBBEN JIM	Acc Dir From City: "N/A"	Distance 2: "N/A"
Badge #: 75-5	Closest City: "N/A"	Direction 2: "N/A"
Report Date: 07/12/2011	Miles From City: "N/A"	X-Coordinate: 00240662
Officer Notified: 11:05 Hrs.	Road, Street, HWay: "N/A"	Y-Coordinate: 04751016
Officer Arrived: 11:19 Hrs.	Definable Location: "N/A"	Location Literal: US 0075 / US 75 MEASURING
Scene Investigated: YES	Milepost Number: "N/A"	Description: 0.15 MILES NORTH FROM US
		0075 / US 75 AND 130TH ST

Unit 001

Driver Name - Last: STRAUSS	Towing: YES	Injury Status: 3 - NON-INCAPACITATING
First: JAYSON	Initial Trvl Dir: 3 - SOUTH	Transported to:
Middle: DAVID	Vision Obscured: 01 - NOT OBSCURED	Transported by:
Address: 6009 WEST 40TH STREET		Emergency Veh: 1 - NOT APPLICABLE
City: SIOUX FALLS	Traffic Controls: 01 - NO CONTROLS PRESENT	Emergency Status: 3 - NOT APPLICABLE
State: SD		Cont. Circum., Drvr: 07 - CROSSED CENTERLINE
Zip: 57106-8706	Point of Init Impact: 01 - FRONT	
Suffix:	Most Damaged Area: 08 - LEFT FRONT	Carrier Name:
Gender: MALE	Undrrid/Ovrid: 1 - NONE	Carrier Address:
Age: 35	Rpr/Rpic Cost: \$15,000.00	Carrier City:
License State: SD	Ext of Damage: 4 - DISABLING DAMAGE	Carrier State:
License Class: 2	First Event: 04 - CROSSED CENTERLINE/MEDIAN	Carrier Zip:
License Endorsmnt: NONE	Second Event: 21 - VEHICLE IN TRAFFIC	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: 0	Third Event:	Number of Axles:
Speed Limit: 55	Fourth Event:	HazMat Released?:
Seating Position: 01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER		GVWR:
Driver Condition: 8 - OTHER (EXPLAIN IN NARRA		Placard #:
Alcohol Test Given: NO		Cit Chrg Code 1: 321.297
Drug Test Given: NO		Citation Charge 1: DRIVING ON WRONG SIDE OF TWO WAY HIGHWAY
Total Occupants: 01	Most Harmful Event: 21 - VEHICLE IN TRAFFIC	Cit Chrg Code 2:
Vehicle Year: 2011	Abg Switch Stat: 3 - NO ON/OFF SWITCH PRESENT	Citation Charge 2:
Vehicle Make: TOYOTA - TOYT	Abg Deploy: 1 - DEPLOYED FRONT OF PERSON	Cit Chrg Code 3:
Vehicle Model: CAMRY	Trapped: 1 - NOT TRAPPED	Citation Charge 3:
Vehicle Style: 4 DOOR	Ejection: 1 - NOT EJECTED	Cit Chrg Code 4:
Vehicle Config: 01 - PASSENGER CAR	Ejection Path: 1 - NOT EJECTED/NOT APPLICABLE	Citation Charge 4:
Vehicle Defect: 01 - NONE	Occpnt Protect: 2 - SHOULDER AND LAP BELT USED	
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		

Unit 002

Driver Name - Last: POLLEMA	Towing: YES	Injury Status: 3 - NON-INCAPACITATING
First: BRANDON	Initial Trvl Dir: 1 - NORTH	Transported to:
Middle: J	Vision Obscured: 01 - NOT OBSCURED	Transported by:
Address: 609 2ND ST		Emergency Veh: 1 - NOT APPLICABLE
City: HULL	Traffic Controls: 01 - NO CONTROLS PRESENT	Emergency Status: 3 - NOT APPLICABLE
State: IA		Cont. Circum., Drvr: 28 - NO IMPROPER ACTION
Zip: 51239-0000	Point of Init Impact: 01 - FRONT	
Suffix:	Most Damaged Area: 08 - LEFT FRONT	Carrier Name:
Gender: MALE	Undrrid/Ovrid: 1 - NONE	Carrier Address:
Age: 37	Rpr/Rpic Cost: \$15,000.00	Carrier City:
License State: IA	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier State:
License Class: A	First Event: 21 - VEHICLE IN TRAFFIC	Carrier Zip:
License Endorsmnt: N - TANK	Second Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: NONE	Third Event:	Number of Axles:
Speed Limit: 55	Fourth Event:	HazMat Released?:
Seating Position: 01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER		GVWR:
Driver Condition: 1 - APPARENTLY NORMAL		Placard #:
Alcohol Test Given: NO		Cit Chrg Code 1:
Drug Test Given: NO		Citation Charge 1:
Total Occupants: 04	Most Harmful Event: 21 - VEHICLE IN TRAFFIC	Cit Chrg Code 2:
Vehicle Year: 2000	Abg Switch Stat: 3 - NO ON/OFF SWITCH PRESENT	Citation Charge 2:
Vehicle Make: CHEVROLET - CHEV	Abg Deploy: 1 - DEPLOYED FRONT OF PERSON	Cit Chrg Code 3:
Vehicle Model: SLV	Trapped: 1 - NOT TRAPPED	Citation Charge 3:
Vehicle Style: 3D	Ejection: 1 - NOT EJECTED	Cit Chrg Code 4:
Vehicle Config: 02 - FOUR-TIRE LIGHT TRUCK (PICK-UP, PANEL)	Ejection Path: 1 - NOT EJECTED/NOT APPLICABLE	Citation Charge 4:
Vehicle Defect: 01 - NONE	Occpnt Protect: 2 - SHOULDER AND LAP BELT USED	
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		

Accident Environment

First Harmful Event Loc: **1 - ON ROADWAY**
 Manner of Crash/Collision: **7 - SIDESWIPE, OPPOSITE DIRECTION**
 Light Conditions: **1 - DAYLIGHT**
 Weather Conditions: **06 - RAIN**

 Surface Conditions: **2 - WET**

 First Harmful Evt of Crash: **21 - VEHICLE IN TRAFFIC**

Roadway Characteristics
 Environment: **1 - NONE APPARENT**
 Roadway: **01 - NONE APPARENT**
 Type of Road Junc/Feat: **01 - NO SPECIAL FEATURE**

 Workzone Related: **NO**
 Location:
 Type:
 Workers Present:

Injured Person 001

Name - Last: **POLLEMA**
 First: **TANNER**
 Middle: **J**
 Suffix:
 Address: **609 2ND STREET**
 City: **HULL**
 State: **IA**
 Zip Code: **51239**
 Age: **13**
 Sex: **MALE**
 Unit No.: **002**
 Seating Position: **03 - FRONT: RIGHT SIDE**
 Injury Status: **3 - NON-INCAPACITATING**
 Transported to:
 Transported by:

Occupant Protection: **2 - SHOULDER AND LAP BELT USED**
 Airbag Deployment: **YES**
 Airbag Switch Status: **3 - NO ON/OFF SWITCH PRESENT**
 Ejection: **1 - NOT EJECTED**
 Ejection Path: **1 - NOT EJECTED/NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED**

Non-Motorist
 Type:
 Location:
 Action:
 Condition:
 Safety Equipment:
 Contributing Circumstances:
 Unit No. of Vehicle Striking:

Injured Person 002

Name - Last: **POLLEMA**
 First: **BRILEY**
 Middle: **J**
 Suffix:
 Address: **609 2ND ST**
 City: **HULL**
 State: **IA**
 Zip Code: **51239**
 Age: **8**
 Sex: **FEMALE**
 Unit No.: **002**
 Seating Position: **02 - FRONT: CENTER**
 Injury Status: **3 - NON-INCAPACITATING**
 Transported to:
 Transported by:

Occupant Protection: **3 - LAP BELT ONLY USED**
 Airbag Deployment: **YES**
 Airbag Switch Status: **3 - NO ON/OFF SWITCH PRESENT**
 Ejection: **1 - NOT EJECTED**
 Ejection Path: **1 - NOT EJECTED/NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED**

Non-Motorist
 Type:
 Location:
 Action:
 Condition:
 Safety Equipment:
 Contributing Circumstances:
 Unit No. of Vehicle Striking:

Narrative

VEHICLE #1 WAS SOUTHBOUND ON HIGHWAY 75 APPROACHING A HILL CREST. ACCORDING TO DRIVER #1, HE WAS ATTEMPTING TO LOCATE A PHONE NUMBER ON HIS CELL PHONE AND LOST TRACK OF HIS POSITION ON THE ROADWAY. VEHICLE #1 VEERED INTO THE OPPOSING LANE AND STRUCK VEHICLE #2 WHICH WAS NORTHBOUND ON HIGHWAY 75 AT THIS SAME LOCATION. ALL INJURIES WERE MINOR AND REQUIRED NO TREATMENT. VEHICLE #1 WAS TOWED TO LE MARS BODY SHOP AND VEHICLE #2 WAS TOWED TO LANGLE BODY SHOP, BOTH IN LE MARS.

Diagram

