

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: SO11002809
 Date of Acc: 12/06/11
 Time of Acc: 06:20 Hrs.
 Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF
 Officer: LUBBEN, JIM
 Badge #: 75-5
 Report Date: 12/06/2011
 Officer Notified: 06:25 Hrs.
 Officer Arrived: 06:57 Hrs.
 Scene Investigated: YES

Legal Intervention: NO
 Private Property: NO
 County: PLYMOUTH - 75
 Acc Loc City:
 Acc Dir From City: "N/A"
 Closest City: "N/A"
 Miles From City: "N/A"
 Road, Street, HWay: "N/A"
 Definable Location: "N/A"
 Milepost Number: "N/A"

At Intersection with: "N/A"
 Div HWay Trvl Dir: "N/A"
 Distance 1: "N/A"
 Direction 1: "N/A"
 Distance 2: "N/A"
 Direction 2: "N/A"
 X-Coordinate: 00213557
 Y-Coordinate: 04731811
 Location Literal: C043 / NORTH RIDGE RD
 Description: MEASURING 45 FEET NORTHEAST FROM C043 / NORTH RIDGE RD AND K018 / K18

Unit 001

Driver Name - Last: MENARD	Towing: YES	Injury Status: 5 - UNINJURED
First: PAUL	Initial Trvl Dir: 3 - SOUTH	Transported to:
Middle: ANTONE	Vision Obscured: 13 - FOG/SMOKE/DUST	Transported by:
Address: 19295 C-44	Traffic Controls: 01 - NO CONTROLS PRESENT	Emergency Veh: 1 - NOT APPLICABLE
City: MERRILL	Point of Init: 01 - FRONT	Emergency Status: 3 - NOT APPLICABLE
State: IA	Impact:	Cont. Circum., Drvr: 28 - NO IMPROPER ACTION
Zip: 51038	Most Damaged Area: 01 - FRONT	Carrier Name:
Suffix:	Undrid/Ovrid: 1 - NONE	Carrier Address:
Gender: MALE	Rpr/Rplc Cost: \$3,000.00	Carrier City:
Age: 53	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier State:
License State: IA	First Event: 25 - ANIMAL	Carrier Zip:
License Class: C	Second Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Endorsmnt: L	Third Event:	Number of Axles:
License Restrictions: NONE	Fourth Event:	HazMat Released?:
Speed Limit: 55	Most Harmful Event: 25 - ANIMAL	GVWR:
Seating Position: 01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER	Abg Switch Stat: 3 - NO ON/OFF SWITCH PRESENT	Placard #:
Driver Condition: 1 - APPARENTLY NORMAL	Abg Deploy: 5 - NOT DEPLOYED	Cit Chrg Code 1:
Alcohol Test Given: NO	Trapped: 1 - NOT TRAPPED	Citation Charge 1:
Drug Test Given: NO	Ejection: 1 - NOT EJECTED	Cit Chrg Code 2:
Total Occupants: 03	Ejection Path: 1 - NOT EJECTED/NOT APPLICABLE	Citation Charge 2:
Vehicle Year: 1993	Occpnt Protect: 2 - SHOULDER AND LAP BELT USED	Cit Chrg Code 3:
Vehicle Make: JEEP - JEEP		Citation Charge 3:
Vehicle Model: CHEROKEE		Cit Chrg Code 4:
Vehicle Style: SUV		Citation Charge 4:
Vehicle Config: 04 - SPORT UTILITY VEHICLE		
Vehicle Defect: 01 - NONE		
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		

Property Damage 001

Object Damaged: HORSE	Company Owner Name:
Estimate of Damage: \$1,000.00	Street or RFD: 16391 NORTH RIDGE ROAD
Owner's Name - Last: BANKS	City: WESTFIELD
First: CHAD	State: IA
Middle: MARSHALL	Zip Code: 51062
Suffix:	

Accident Environment

First Harmful Event Loc: 1 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 1 - NON-COLLISION	Environment: 6 - ANIMAL IN ROADWAY
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 02 - ROAD SURFACE CONDITION
Weather Conditions: 04 - FOG, SMOKE	Type of Road Junc/Feat: 11 - FOUR-WAY INTERSECTION
Surface Conditions: 3 - ICE	Workzone Related: NO
First Harmful Evt of Crash: 25 - ANIMAL	Location:
	Type:
	Workers Present:

Injured Person 001

Name - Last:	MENARD	Occupant Protection:	2 - SHOULDER AND LAP BELT USED
First:	CAROLINE	Airbag Deployment:	6
Middle:	MAE	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	19255 C-44	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	MERRILL	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51038	Non-Motorist	
Age:	19	Type:	
Sex:	FEMALE	Location:	
Unit No.:	001	Action:	
Seating Position:	03 - FRONT: RIGHT SIDE	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	RESIDENCE	Contributing Circumstances:	
Transported by:	PRIVATE VEHICLE	Unit No. of Vehicle Striking:	

Narrative

VEHICLE #1 WAS SOUTHBOUND ON K-18 IN LIGHT FOG AND ON THE ICE COVERED ROADWAY. AS HE APPROACHED C-43, THE DRIVER CAME UPON SEVERAL HORSES IN THE ROADWAY. HE WAS UNABLE TO STOP AND STRUCK AT LEAST ONE OF THE ANIMALS, KILLING IT AND DEPOSITING IT ON THE ROADWAY IN THE NORTHBOUND LANE, SOUTH OF THE INTERSECTION. THE VEHICLE CAME TO REST ON THE EAST SHOULDER, JUST SOUTH OF THE INTERSECTION. THE PASSENGER WAS SHOWERED WITH GLASS FROM THE WINDSHIELD AND WAS TAKEN HOME TO BE CHECKED. SHE WILL BE TAKEN TO A MEDICAL FACILITY LATER IF WARRANTED. THE VEHICLE WAS TOWED BY LEMARS BODY SHOP.

Diagram

