

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: SO11002837	Legal Intervention: NO	At Intersection with: "N/A"
Date of Acc: 12/07/11	Private Property: NO	Div HWay Trvl Dir: "N/A"
Time of Acc: 21:15 Hrs.	County: PLYMOUTH - 75	Distance 1: "N/A"
Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF	Acc Loc City:	Direction 1: "N/A"
Officer: DORHOUT, S	Acc Dir From City: "N/A"	Distance 2: "N/A"
Badge #: 75-7	Closest City: "N/A"	Direction 2: "N/A"
Report Date: 12/07/2011	Miles From City: "N/A"	X-Coordinate: 00236305
Officer Notified: 21:15 Hrs.	Road, Street, HWay: "N/A"	Y-Coordinate: 04736537
Officer Arrived: 21:25 Hrs.	Definable Location: "N/A"	Location Literal: NB/EB US 0075 / US 75
Scene Investigated: YES	Milepost Number: "N/A"	Description: (MILEPOST 114)

Unit 001

Driver Name - Last: RAMIREZ PENA First: PEDRO Middle: Address: 319 S RIDGE DR City: SOUTH SIOUX CITY State: NE Zip: 68776-0000 Suffix: Gender: MALE Age: 37 License State: NE License Class: O License Endorsmnt: NONE License Restrictions: B Speed Limit: Seating Position: Driver Condition: Alcohol Test Given: NO Drug Test Given: NO Total Occupants: Vehicle Year: 2001 Vehicle Make: CHRYSLER - CHRY Vehicle Model: TOWN & COUNTRY Vehicle Style: SPORT VAN Vehicle Config: Vehicle Defect: Vehicle Action:	Towing: YES Initial Trvl Dir: Vision Obscured: Traffic Controls: Point of Init Impact: Most Damaged Area: Undrld/Ovrid: Rpr/Rplc Cost: \$5,000.00 Ext of Damage: First Event: Second Event: Third Event: Fourth Event: Most Harmful Event: Abg Switch Stat: Abg Deploy: Trapped: Ejection: Ejection Path: Occpnt Protect:	Injury Status: Transported to: Transported by: Emergency Veh: Emergency Status: Cont. Circum., Drvr: Carrier Name: Carrier Address: Carrier City: Carrier State: Carrier Zip: Cargo Body Type: Number of Axles: HazMat Released?: GVWR: Placard #: Cit Chrg Code 1: Citation Charge 1: Cit Chrg Code 2: Citation Charge 2: Cit Chrg Code 3: Citation Charge 3: Cit Chrg Code 4: Citation Charge 4:
---	--	---

Accident Environment

First Harmful Event Loc: Manner of Crash/Collision: Light Conditions: Weather Conditions: Surface Conditions: First Harmful Evt of Crash: 25 - ANIMAL	Roadway Characteristics Environment: Roadway: Type of Road Junc/Feat: Workzone Related: Location: Type: Workers Present:
---	--

Narrative

VEHICLE #1 WAS NORTHBOUND ON HIGHWAY #75 WHEN A DEER CAME INTO ITS PATH. #1 WAS UNABLE TO AVOID THE DEER AND STRUCK IT WITH ITS FRONT END.