

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	SO11002925	Legal Intervention:	NO	At Intersection with:	"N/A"
Date of Acc:	12/18/11	Private Property:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	06:45 Hrs.	County:	PLYMOUTH - 75	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	Acc Loc City:		Direction 1:	"N/A"
Officer:	VERMEYS, JARY	Acc Dir From City:	"N/A"	Distance 2:	"N/A"
Badge #:	75-8	Closest City:	"N/A"	Direction 2:	"N/A"
Report Date:	12/18/2011	Miles From City:	"N/A"	X-Coordinate:	00247719
Officer Notified:	06:51 Hrs.	Road, Street, HWay:	"N/A"	Y-Coordinate:	04753785
Officer Arrived:	07:00 Hrs.	Definable Location:	"N/A"	Location Literal:	IOWA 0060 / IOWA 60
Scene Investigated:	YES	Milepost Number:	"N/A"	Description:	MEASURING 53 YARDS SOUTHWEST FROM C012 / 110TH ST AND IOWA 0060 / IOWA 60 AND 110TH ST

Unit 001

Driver Name - Last:	GAMBOA	Towing:	YES	Injury Status:	5 - UNINJURED
First:	JAKOB	Initial Trvl Dir:	1 - NORTH	Transported to:	
Middle:	DENZELL	Vision Obscured:	01 - NOT OBSCURED	Transported by:	
Address:	613 OAK ST	Traffic Controls:	01 - NO CONTROLS PRESENT	Emergency Veh:	1 - NOT APPLICABLE
City:	SHELDON	Point of Init Impact:	09 - TOP	Emergency Status:	3 - NOT APPLICABLE
State:	IA	Most Damaged Area:	09 - TOP	Cont. Circum., Drvr:	08 - LOST CONTROL, 10 - SWERV
Zip:	51201	Undrtd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$9,000.00	Carrier Address:	
Gender:	MALE	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	20	First Event:	06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, ETC.)	Carrier State:	
License State:	IA	Second Event:	05 - ANIMAL OR OBJECT IN ROADWAY	Carrier Zip:	
License Class:	C	Third Event:	11 - OVERTURN/ROLLOVER	Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	NONE	Most Harmful Event:	11 - OVERTURN/ROLLOVER	HazMat Released?:	
Speed Limit:	65	Abg Switch Stat:	3 - NO ON/OFF SWITCH PRESENT	GVWR:	
Seating Position:	01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER	Abg Deploy:	5 - NOT DEPLOYED	Placard #:	
Driver Condition:	1 - APPARENTLY NORMAL	Trapped:	1 - NOT TRAPPED	Cit Chrg Code 1:	
Alcohol Test Given:	NO	Ejection:	1 - NOT EJECTED	Citation Charge 1:	
Drug Test Given:	NO	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE	Citation Charge 2:	
Total Occupants:	7	Occpnt Protect:	2 - SHOULDER AND LAP BELT USED	Citation Charge 3:	
Vehicle Year:	2004			Citation Charge 4:	
Vehicle Make:	GENERAL MOTORS - GMC				
Vehicle Model:	ENVOY XL				
Vehicle Style:	SUV				
Vehicle Config:	04 - SPORT UTILITY VEHICLE				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				

Accident Environment

First Harmful Event Loc:	1 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	1 - NON-COLLISION	Environment:	6 - ANIMAL IN ROADWAY
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR, 10 - BLOWING SAND, SOIL, DIRT, SNOW	Type of Road Junc/Feat:	01 - NO SPECIAL FEATURE
Surface Conditions:	1 - DRY	Workzone Related:	NO
First Harmful Evt of Crash:	11 - OVERTURN/ROLLOVER	Location:	
		Type:	
		Workers Present:	

Injured Person 001

Name - Last:	TRIJUQUE	Occupant Protection:	2 - SHOULDER AND LAP BELT USED
First:	JUSTINE	Airbag Deployment:	5
Middle:	J	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	310 PARK ST	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	SHELDON	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51201	Non-Motorist	
Age:	17	Type:	
Sex:	FEMALE	Location:	
Unit No.:	001	Action:	
Seating Position:	03 - FRONT: RIGHT SIDE	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	FLOYD VALLEY, LEMARS	Contributing Circumstances:	
Transported by:	LEMARS AMBULANCE	Unit No. of Vehicle Striking:	

Injured Person 002

Name - Last:	LEIKVOLD	Occupant Protection:	9 - UNKNOWN
First:	AMANDA	Airbag Deployment:	5
Middle:	L	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	4345 340TH ST	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	SHELDON	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51201	Non-Motorist	
Age:	19	Type:	
Sex:	FEMALE	Location:	
Unit No.:	001	Action:	
Seating Position:	04 - CENTER: LEFT SIDE / MOTORCYCLE PASSENGER	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	FLOYD VALLEY, LEMARS	Contributing Circumstances:	
Transported by:	LEMARS AMBULANCE	Unit No. of Vehicle Striking:	

Injured Person 003

Name - Last:	SCHUTTLER	Occupant Protection:	9 - UNKNOWN
First:	BETHANY	Airbag Deployment:	5
Middle:	M	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	516 8TH ST	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	SIBLEY	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51249	Non-Motorist	
Age:	19	Type:	
Sex:	FEMALE	Location:	
Unit No.:	001	Action:	
Seating Position:	05 - CENTER: CENTER	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	NO TRANSPORT	Contributing Circumstances:	
Transported by:		Unit No. of Vehicle Striking:	

Injured Person 004

Name - Last:	SCOTT	Occupant Protection:	1 - NONE USED
First:	RAYFORD	Airbag Deployment:	5
Middle:	A	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	613 OAK ST	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	SHELDON	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51201	Non-Motorist	
Age:	19	Type:	
Sex:	MALE	Location:	
Unit No.:	001	Action:	
Seating Position:	08 - REAR: CENTER	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	NO TRANSPORT	Contributing Circumstances:	
Transported by:		Unit No. of Vehicle Striking:	

Injured Person 005

Name - Last:	SCHMITH	Occupant Protection:	1 - NONE USED
First:	CODY	Airbag Deployment:	YES
Middle:	T	Airbag Switch Status:	3 - NO ON/OFF SWITCH PRESENT
Suffix:		Ejection:	1 - NOT EJECTED
Address:	2729 KENNEDY AVE	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE
City:	BOYDEN	Trapped:	1 - NOT TRAPPED
State:	IA		
Zip Code:	51234	Non-Motorist	
Age:	19	Type:	
Sex:	MALE	Location:	
Unit No.:	001	Action:	
Seating Position:	09 - REAR: RIGHT SIDE	Condition:	
Injury Status:	4 - POSSIBLE	Safety Equipment:	
Transported to:	NO TRANSPORT	Contributing Circumstances:	
Transported by:		Unit No. of Vehicle Striking:	

Injured Person 006

Name - Last: LEWCHUK
 First: ALISA
 Middle: L
 Suffix:
 Address: 1000 LINCOLN AVE
 City: SHELDON
 State: IA
 Zip Code: 51201
 Age: 20
 Sex: FEMALE
 Unit No.: 001
 Seating Position: 07 - REAR: LEFT SIDE
 Injury Status: 4 - POSSIBLE
 Transported to: NO TRANSPORT
 Transported by:

Occupant Protection: 1 - NONE USED
 Airbag Deployment: 5
 Airbag Switch Status: 3 - NO ON/OFF SWITCH PRESENT
 Ejection: 1 - NOT EJECTED
 Ejection Path: 1 - NOT EJECTED/NOT APPLICABLE
 Trapped: 1 - NOT TRAPPED

Non-Motorist
 Type:
 Location:
 Action:
 Condition:
 Safety Equipment:
 Contributing Circumstances:
 Unit No. of Vehicle Striking:

Narrative

VEHICLE 1 WAS TRAVELING NORTHBOUND ON HWY 60. A DEER CAME ONTO THE ROADWAY, DRIVER OF VEHICLE 1 PANIC SWERVED TO AVOID CONTACT WITH THE DEER, LOST CONTROL OF VEHICLE 1 AND ROLLED THE VEHICLE 1.5 TIMES ON THE TRAVELED PORTION OF HWY 60. THE VEHICLE DID COME TO REST ON THE EAST SHOULDER ON ITS TOP. ALL OCCUPANTS WERE ABLE TO EXIT VEHICLE 1. INJURED PARTIES RECEIVED MINOR CUTS TO FACE AND HANDS AND ALSO COMPLAINED OF BACK PAIN AT THE TIME OF THE ACCIDENT.

Diagram

