

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-009360	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	09/01/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	15:26 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	"N/A"
Officer:	BARTOLOZZI CRAIG	Acc Loc City:		Distance 2:	"N/A"
Badge #:	75-2	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	09/01/2016	Closest City:	"N/A"	X-Coordinate:	00258164
Officer Notified:	15:26 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04743742
Officer Arrived:	15:33 Hrs.	Road, Street, HWay:	"N/A"	Location Literal Description:	STATE 3/IOWA 3 AND STATE 140/IOWA 140 AND L014/L14
Scene Investigated:	YES	Definable Location:	"N/A"		
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	PLAGMAN	Bus Use:		Transported to:	
First:	ELLEN	Drvr Distractions:	01 - NOT APPLICABLE/NO DRIVER	Transported by:	
Middle:	LEE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	CLEGHORN	Point of Init Impact:	09 - MIDDLE DRIVER SIDE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	51014	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$2,000.00		
Gender:	Female	Ext of Damage:	2 - MINOR DAMAGE		
Age:	58	First Event:	33 - VEHICLE IN TRAFFIC	Carrier Name:	
CDL:	NO	Second Event:		Carrier Address:	
License State:	IA	Third Event:		Carrier City:	
License Class:	C	Fourth Event:		Carrier State:	
License Endorsmnt:	NONE	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	Carrier Zip:	
License Restrictions:	NONE	Abg Switch Stat:		Cargo Body Type:	01 - NOT APPLICABLE
Speed Limit:	55	Abg Deploy:	01 - NOT APPLICABLE	Number of Axles:	
Seating Position:	01 - 1ST ROW; LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Involvement:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	1 - NOT APPLICABLE	HazMat Placard:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Placard #:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	HazMat Released?:	
Total Occupants:	1	Injury Status:	5 - UNINJURED	Converter Dolly:	
Vehicle Year:	2011	Source of Trans:	01 - NOT TRANSPORTED	GVWR:	
Vehicle Make:	FORD - FORD	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 1:	
Vehicle Model:	FUSION			Citation Charge 1:	
Vehicle Style:	4D			Cit Chrg Code 2:	
Vehicle Color:	WHITE - WHI			Citation Charge 2:	
Vehicle Config:	01 - PASSENGER CAR			Cit Chrg Code 3:	
Vehicle Defect:	01 - NONE			Citation Charge 3:	
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT			Cit Chrg Code 4:	
Tow:	1 - DRIVEN AWAY			Citation Charge 4:	
Tow #:					
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last:	TENTINGER	Bus Use:		Transported to:	
First:	ABIGAL	Drvr Distractions:	16 - LOOKED BUT DID NOT SEE	Transported by:	
Middle:	CHRISTINE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	REMSEN	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	42 - FTYROW: MAKING LEFT TURN
Zip:	51050	Undrid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpt/Rplc Cost:	\$200.00	Carrier Address:	
Gender:	Female	Ext of Damage:	2 - MINOR DAMAGE	Carrier City:	
Age:	16	First Event:	33 - VEHICLE IN TRAFFIC	Carrier State:	
CDL:	NO	Second Event:		Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:	NONE	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
License Restrictions:	Y	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	01 - NOT APPLICABLE	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	1 - NOT APPLICABLE	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occup Protct:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	321.320
Total Occupants:	1	Injury Status:	5 - UNINJURED	Citation Charge 1:	FAIL TO YIELD UPON LEFT TURN
Vehicle Year:	1995	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 2:	
Vehicle Make:	CHEVROLET - CHEV	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Model:	LUMINA			Cit Chrg Code 3:	
Vehicle Style:	4D			Citation Charge 3:	
Vehicle Color:	GREEN - GRN			Cit Chrg Code 4:	
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 4:	
Vehicle Defect:	01 - NONE				
Vehicle Action:	02 - TURNING LEFT				
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	04 - ANGLE, ONCOMING LEFT TURN	Environment:	01 - NONE APPARENT
Light Conditions:	1 - DAYLIGHT	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	33 - VEHICLE IN TRAFFIC
Type:			
Workers Present:			

Narrative

Vehicle #1 was traveling west on #3 at the intersection of #140 and #3. Vehicle #2 was traveling east on #3 and was going to make a left turn onto county road L-14. Driver of #2 stated she looked and did not see vehicle #1 and struck vehicle #1 in the driver side.

