

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	16011139	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	10/23/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	21:30 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	"N/A"
Officer:	DORHOUT SCOTT	Acc Loc City:		Distance 2:	"N/A"
Badge #:	75-6	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	10/23/2016	Closest City:	"N/A"	X-Coordinate:	00223760
Officer Notified:	21:34 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04727325
Officer Arrived:	21:55 Hrs.	Road,Street,HWay:	"N/A"	Location Literal Description:	280TH ST MEASURING 389 FEET EAST FROM 280TH ST AND K022/K22
Scene Investigated:	YES	Definable Location:	"N/A"		
		Milepost Number:	"N/A"		

**Unit 001**

Driver Name - Last:	ROSLANSKY	Bus Use:		Transported to:	ST LUKES HOSPITAL
First:	MORIAH	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	PARENT
Middle:	EVE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	HINTON	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51024-0000	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$4,000.00	Carrier Name:	
Gender:	Female	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier Address:	
Age:	17	First Event:	33 - VEHICLE IN TRAFFIC	Carrier City:	
CDL:	NO	Second Event:	04 - CROSSED CENTERLINE (UNDIVIDED)	Carrier State:	
License State:	IA	Third Event:	42 - BRIDGE/BRIDGE RAIL PARAPET	Carrier Zip:	
License Class:	C	Fourth Event:	44 - DITCH	Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Most Harmful Event:	42 - BRIDGE/BRIDGE RAIL PARAPET	Number of Axles:	
License Restrictions:	NONE	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	50	Abg Deploy:	06 - DEPLOYED BOTH FRONT/SIDE	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Total Occupants:	01	Injury Status:	4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)	Citation Charge 1:	
Vehicle Year:	2002	Source of Trans:	05 - PARENT/SPOUSE/FRIEND	Cit Chrg Code 2:	
Vehicle Make:	PONTIAC - PONT	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Model:	GRA			Cit Chrg Code 3:	
Vehicle Style:	4D			Citation Charge 3:	
Vehicle Color:	SILVER - SIL			Cit Chrg Code 4:	
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 4:	
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	16000404				
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

**Property Damage**

Object Damaged:	SIGN	Company Owner Name:	PLYMOUTH COUNTY
Estimate of Damage:	\$100.00	City:	LEMARS
Owner's Name - Last:		State:	IA
First:		Zip Code:	51031
Middle:			
Suffix:			

**Accident Environment**

First Harmful Event Loc:	01 - ON ROADWAY	<b>Roadway Characteristics</b>	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	08 - SAND	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	33 - VEHICLE IN TRAFFIC
Type:			
Workers Present:			

**Narrative**

Vehicle #1 was westbound on 280th Street. #1 lost control on the gravel road and crossed the road, striking the south side of a bridge before coming to rest in the south ditch.

