

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-011454	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	11/02/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	10:45 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	"N/A"
Officer:	BETSWORTH PAUL	Acc Loc City:	"N/A"	Distance 2:	"N/A"
Badge #:	75-5	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	11/02/2016	Closest City:	"N/A"	X-Coordinate:	00232377
Officer Notified:	10:46 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04744057
Officer Arrived:	10:59 Hrs.	Road, Street, HWay:	"N/A"	Location Literal:	K042/K42 MEASURING 3303 FEET NORTH FROM STATE 3/IOWA 3 AND K042/K42
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	RENKEN	Bus Use:		Transported to:	FLOYD VALLEY HOSPITAL
First:	RODNEY	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	LEMARS AMBULANCE
Middle:	ROMAIN	Traffic Controls:	06 - NO PASSING ZONE (MARKED)	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	LE MARS	Point of Init Impact:	07 - REAR DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	51031	Undridd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$10,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	73	First Event:	33 - VEHICLE IN TRAFFIC	Carrier State:	
CDL:	NO	Second Event:		Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	A	Fourth Event:		Number of Axles:	
License Endorsmnt:	P - PASS, N - TANK	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
License Restrictions:	M, B	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	01 - NOT APPLICABLE	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	02 - NONE USED	Cit Chrg Code 1:	
Total Occupants:	1	Injury Status:	4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)	Citation Charge 1:	
Vehicle Year:	1970	Source of Trans:	03 - EMS GROUND	Citation Charge 2:	
Vehicle Make:	JOHN DEERE - DEER	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 3:	
Vehicle Model:	4020			Citation Charge 4:	
Vehicle Style:	TRACTOR				
Vehicle Color:	GREEN - GRN				
Vehicle Config:	26 - FARM TRACTOR				
Vehicle Defect:	01 - NONE				
Vehicle Action:	02 - TURNING LEFT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: DOWDY	Bus Use:	Transported to:
First: NATHAN		
Middle: EDWARD	Drvr Distractons: 02 - NOT DISTRACTED	Transported by:
City: MC CALLSBURG		
State: IA	Traffic Controls: 06 - NO PASSING ZONE (MARKED)	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 50154		
Suffix:	Point of Init Impact: 04 - REAR PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 04 - REAR PASSENGER SIDE	Cont. Circum., Drvr: 07 - FOLLOWED TOO CLOSE, 31 - PASSING: WHERE PROHIBITED BY SIGNS/MARKINGS
Age: 25	Undrrld/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rpic Cost: \$8,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name: KUNKEL EXPRESS LLC
License Endorsmnt: N - TANK		Carrier Address: 20976 KALE DR
License Restrictions: J,1		Carrier City: LE MARS
Speed Limit: 55		Carrier State: IA
Seating Positlon: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Zip: 51031
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 04 - CARGO TANK
Alcohol Test Given: YES	Third Event:	
Drug Test Given: 1 - NONE		Number of Axles: 5
Total Occupants: 2	Fourth Event:	HazMat Involvement: 02 - NO
Vehicle Year: 2006		HazMat Placard:
Vehicle Make: PETERBILT - PTRB	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Model: SEMI TRUCK		HazMat Released?:
Vehicle Style: SEMI	Abg Switch Stat:	Converter Dolly:
Vehicle Color: WHITE - WHI	Abg Deploy: 03 - NOT DEPLOYED	GVWR: 3 - 26,001 LBS OR MORE
Vehicle Config: 13 - TRACTOR/SEMI-TRAILER		Cit Chrg Code 1: 321.285
Vehicle Defect: 01 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1: FAILURE TO STOP IN ASSURED CLEAR DISTANCE
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection: 2 - NOT EJECTED	
Tow: 1 - DRIVEN AWAY	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow #:	Injury Status: 5 - UNINJURED	Cit Chrg Code 3:
Initial Trvl Dir: 03 - SOUTH		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 4:
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

vehicle #1, a farm tractor pulling two gravity wagons was southbound on k-42 and had started to pull into a farm field. vehicle #2, a semi pulling a tanker was also southbound on k-42. the driver of vehicle #2 stated he didn't see vehicle #1 and wasn't going to get slowed down in time so he decided to go around vehicle #1 in a no passing zone. vehicle #1 was pulling into the farm field drive at that time and the vehicles collided.

