

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>16011759</b>	Report to All Drivers: <b>NO</b>	At Intersection with: <b>"N/A"</b>
Date of Acc: <b>11/10/16</b>	Legal Intervention: <b>NO</b>	Div HWay Trvl Dir: <b>"N/A"</b>
Time of Acc: <b>12:00</b> Hrs.	Private Property: <b>NO</b>	Distance 1: <b>"N/A"</b>
Name of Agency: <b>PLYMOUTH COUNTY SHERIFF'S OFF</b>	County: <b>PLYMOUTH - 75</b>	Direction 1: <b>"N/A"</b>
Officer: <b>TEBRINK JEFF</b>	Acc Loc City:	Distance 2: <b>"N/A"</b>
Badge #: <b>75-3</b>	Acc Dir From City: <b>"N/A"</b>	Direction 2: <b>"N/A"</b>
Report Date: <b>11/10/2016</b>	Closest City: <b>"N/A"</b>	X-Coordinate: <b>00246546</b>
Officer Notified: <b>12:05</b> Hrs.	Miles From City: <b>"N/A"</b>	Y-Coordinate: <b>04737540</b>
Officer Arrived: <b>12:10</b> Hrs.	Road, Street, HWay: <b>"N/A"</b>	Location Literal: <b>NOBLE AVE MEASURING 463 FEET SOUTH FROM NOBLE AVE AND C038/C38</b>
Scene Investigated: <b>YES</b>	Definable Location: <b>"N/A"</b>	Description:
	Milepost Number: <b>"N/A"</b>	

**Unit 001**

Driver Name - Last: <b>BOHALL</b>	Bus Use:	Transported to: <b>FLOYD VALLEY HOSPITAL LEMARS</b>
First: <b>MARCUS</b>	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by: <b>LEMARS AMBULANCE</b>
Middle: <b>LEE</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
City: <b>MERIDEN</b>	Point of Init Impact: <b>99 - UNKNOWN</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
State: <b>IA</b>	Most Damaged Area: <b>13 - TOP OF VEHICLE</b>	Cont. Circum., Drvr: <b>06 - LOST CONTROL</b>
Zip: <b>51037</b>	Undrriid/Ovrid: <b>1 - NONE</b>	
Suffix:	Rpr/Rplc Cost: <b>\$10,000.00</b>	Carrier Name: <b>NILLES 5 LLC</b>
Gender: <b>Male</b>	Ext of Damage: <b>5 - SEVERE, VEHICLE TOTALED</b>	Carrier Address: <b>19527 L12</b>
Age: <b>21</b>	First Event: <b>01 - RAN OFF ROAD, RIGHT</b>	Carrier City: <b>REMSEN</b>
CDL: <b>YES</b>	Second Event: <b>20 - OVERTURN/ROLLOVER</b>	Carrier State: <b>IA</b>
License State: <b>IA</b>	Third Event:	Carrier Zip: <b>51050</b>
License Class: <b>A</b>	Fourth Event:	Cargo Body Type: <b>04 - CARGO TANK</b>
License Endorsmnt: <b>N - TANK</b>	Most Harmful Event: <b>20 - OVERTURN/ROLLOVER</b>	Number of Axles: <b>5</b>
License Restrictions: <b>NONE</b>	Abg Switch Stat: <b>01 - NOT APPLICABLE</b>	HazMat Involvement:
Speed Limit: <b>55</b>	Abg Deploy: <b>01 - NOT APPLICABLE</b>	HazMat Placard:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped: <b>3 - EXTRICATED BY MECHANICAL</b>	Placard #:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Ejection: <b>2 - NOT EJECTED</b>	HazMat Released?:
Alcohol Test Given: <b>NO</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Converter Dolly: <b>2</b>
Drug Test Given: <b>1 - NONE</b>	Occpnt Protect: <b>02 - NONE USED</b>	GVWR: <b>3 - 26,001 LBS OR MORE</b>
Total Occupants: <b>01</b>	Injury Status: <b>3 - SUSPECTED MINOR/NON-INCAPACITATING</b>	Cit Chrg Code 1: <b>321.288(1)</b>
Vehicle Year: <b>1993</b>	Source of Trans: <b>03 - EMS GROUND</b>	Citation Charge 1: <b>FAILURE TO MAINTAIN CONTROL</b>
Vehicle Make: <b>FREI</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:
Vehicle Model: <b>CONVENTIONAL FL SEMI TRACTOR</b>		Citation Charge 2:
Vehicle Style: <b>WHITE - WHI</b>		Cit Chrg Code 3:
Vehicle Color: <b>13 - TRACTOR/SEMI-TRAILER</b>		Citation Charge 3:
Vehicle Config:		Cit Chrg Code 4:
Vehicle Defect: <b>01 - NONE</b>		Citation Charge 4:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		
Tow: <b>3 - DISABLED - OFFICER ARRANGED</b>		
Tow #: <b>16000435</b>		
Initial Trvl Dir: <b>01 - NORTH</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Property Damage**

Object Damaged: <b>1995 BEALL TANKER TRAILER</b>	Company Owner Name: <b>NILLES 5 LLC</b>
Estimate of Damage: <b>\$20,000.00</b>	City: <b>REMSEN</b>
Owner's Name - Last:	State: <b>IA</b>
First:	Zip Code: <b>51050</b>
Middle:	
Suffix:	

**Accident Environment**

First Harmful Event Loc: <b>04 - ROADSIDE</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>01 - NON-COLLISION (SINGLE VEHICLE)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>20 - OVERTURN/ROLLOVER</b>
Type:	
Workers Present:	

**Narrative**

Vehicle #1 was traveling north on Noble Ave. Vehicle #1 dropped off of the traveled portion and rolled over 3/4 of a turn coming to rest in the east ditch. Driver #1 does not remember why he left the traveled portion of the roadway. Vehicle #1 was loaded with raw manure which did spill into a small creek. Department of Natural Resources was contacted and informed of the manure spill.

**Diagram**

