

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 16-012687	Report to All Drivers: YES	At Intersection with: "N/A"
Date of Acc: 12/03/16	Legal Intervention: NO	Div HWay Trvl Dir: "N/A"
Time of Acc: 21:03 Hrs.	Private Property: NO	Distance 1: "N/A"
Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF	County: PLYMOUTH - 75	Direction 1: "N/A"
Officer: DEPUTY MATT M STRUVE	Acc Loc City: "N/A"	Distance 2: "N/A"
Badge #: 75-10	Acc Dir From City: "N/A"	Direction 2: "N/A"
Report Date: 12/03/2016	Closest City: "N/A"	X-Coordinate: 00236393
Officer Notified: 21:03 Hrs.	Miles From City: "N/A"	Y-Coordinate: 04736602
Officer Arrived: 21:16 Hrs.	Road, Street, HWay: "N/A"	Location Lateral Description: US 75 MEASURING 4405 FEET NORTHEAST FROM US 75 AND KESTREL AVE
Scene Investigated: YES	Definable Location: "N/A"	
	Milepost Number: "N/A"	

Unit 001

Driver Name - Last: MILLER	Bus Use:	Transported to: NONE
First: JOYCE		
Middle: BONNIE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: NONE
City: SIOUX CITY		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51106-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 39	Undrird/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rpic Cost: \$10,000.00	
License State: IA	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Class: C	First Event: 31 - ANIMAL	Carrier Name:
License Endorsmnt: NONE		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit: 65	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Most Harmful Event: 31 - ANIMAL	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Abg Switch Stat:	
Drug Test Given: 1 - NONE	Abg Deploy: 06 - DEPLOYED BOTH FRONT/SIDE	Number of Axles:
Total Occupants: 1	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Involvement:
Vehicle Year: 2014	Ejection: 2 - NOT EJECTED	HazMat Placard:
Vehicle Make: FORD - FORD	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Placard #:
Vehicle Model: FUS	Occupnt Protect: 03 - SHOULDER AND LAP BELT USED	HazMat Released?:
Vehicle Style: SD	Injury Status: 4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)	Converter Dolly:
Vehicle Color: BLACK - BLK	Source of Trans: 01 - NOT TRANSPORTED	GVWR:
Vehicle Config: 01 - PASSENGER CAR	Died at Scene: 01 - NOT APPLICABLE	Clt Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Clt Chrg Code 2:
Tow: 3 - DISABLED - OFFICER ARRANGED		Citation Charge 2:
Tow #: 464		Clt Chrg Code 3:
Initial Trvl Dir: 03 - SOUTH		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		Clt Chrg Code 4:
		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics Environment: 06 - ANIMAL IN ROADWAY
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Roadway: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Weather Conditions: 05 - RAIN	FRA No.:
Surface Conditions: 02 - WET	Horizontal Alignment:
Workzone Related: NO	Vertical Alignment:
Activity:	First Harmful Evt of Crash: 31 - ANIMAL
Location:	
Type:	
Workers Present:	

Narrative

Unit 1 was southbound on hwy 75. A deer was crossing from the west side of hwy 75 to the east side of hwy 75 and crossed into the path of unit 1. Unit 1 impacted the deer causing substantial damage to unit 1. The driver of unit 1 had minor injuries.

