

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	17003479	Report to All Drivers:	NO	At Intersection with:	"N/A"
Date of Acc:	04/05/17	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	23:10 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	"N/A"
Officer:	TEBRINK JEFF	Acc Loc City:		Distance 2:	"N/A"
Badge #:	75-3	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	04/05/2017	Closest City:	"N/A"	X-Coordinate:	00257767
Officer Notified:	23:12 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04745315
Officer Arrived:	23:26 Hrs.	Road, Street, HWay:	"N/A"	Location Literal Description:	160TH ST MEASURING 1602 FEET WEST FROM 160TH ST AND L014/L14
Scene Investigated:	YES	Definable Location:	"N/A"		
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	KAMPFE	Bus Use:		Transported to:	
First:	DALLAS	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	JAMES	Traffic Controls:	07 - WARNING SIGN	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	LE MARS	Point of Init Impact:	14 - UNDERCARRIAGE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51031	Undrriid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$7,800.00	Carrier Name:	
Gender:	Male	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Address:	
Age:	26	First Event:	03 - RAN OFF ROAD, LEFT	Carrier City:	
CDL:	NO	Second Event:	01 - RAN OFF ROAD, RIGHT	Carrier State:	
License State:	IA	Third Event:	47 - CULVERT/PIPE OPENING	Carrier Zip:	
License Class:	C	Fourth Event:	20 - OVERTURN/ROLLOVER	Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Most Harmful Event:	20 - OVERTURN/ROLLOVER	Number of Axles:	
License Restrictions:	B	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	06 - UNDER THE INFLUENCE OF ALCOHOL	Ejection:	2 - NOT EJECTED	HazMat Released?:	
Alcohol Test Given:	YES	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	02 - NONE USED	GVWR:	
Total Occupants:	01	Injury Status:	5 - UNINJURED	Cit Chrg Code 1:	321.288(1)
Vehicle Year:	2007	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Make:	NISSAN - NISS	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Model:	ALTIMA 3.5 SE/3			Citation Charge 2:	
Vehicle Style:	4D			Cit Chrg Code 3:	
Vehicle Color:	BLACK - BLK			Citation Charge 3:	
Vehicle Config:	01 - PASSENGER CAR			Cit Chrg Code 4:	
Vehicle Defect:	01 - NONE			Citation Charge 4:	
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	17000123				
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	04 - ROADSIDE	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	47 - CULVERT/PIPE OPENING
Type:			
Workers Present:			

Narrative

Vehicle #1 was traveling east on 160th St. Vehicle #1 lost control entering a curve and entered the left shoulder. Vehicle #1 then slid out of control across both lanes of traffic and entered the south ditch. Vehicle #1 then continued east in the ditch and struck a cement culvert causing vehicle #1 to roll over 3/4 of a turn. Vehicle #1 came to rest on its driver's side. Driver #1 was arrested for Operating While Intoxicated and Failure to Maintain Control.

