

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	17005744	Report to All Drivers:	NO	At Intersection with:	"N/A"
Date of Acc:	05/31/17	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	21:00 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	PLYMOUTH COUNTY SHERIFF'S OFF	County:	PLYMOUTH - 75	Direction 1:	"N/A"
Officer:	SINGER RICK	Acc Loc City:		Distance 2:	"N/A"
Badge #:	75-4	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	05/31/2017	Closest City:	"N/A"	X-Coordinate:	00210615
Officer Notified:	21:32 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04727668
Officer Arrived:	21:49 Hrs.	Road,Street,HWay:	"N/A"	Location Literal Description:	STATE 12/IOWA 12 MEASURING 771 FEET SOUTHEAST FROM STATE 12/IOWA 12 AND 280TH ST
Scene Investigated:	YES	Definable Location:	"N/A"		
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	VAN GROUW	Bus Use:		Transported to:	MERCY
First:	AUDREY	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	AKRON EMS
Middle:	HELENE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	ORANGE CITY	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	08 - OPERATING VEHICLE IN A RECKLESS, ERRATIC, CARELESS, NEGLIGENT MANNER
Zip:	51041	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$2,500.00	Carrier Name:	
Gender:	Female	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Address:	
Age:	77	First Event:	03 - RAN OFF ROAD, LEFT	Carrier City:	
CDL:	NO	Second Event:	44 - DITCH	Carrier State:	
License State:	IA	Third Event:	45 - EMBANKMENT	Carrier Zip:	
License Class:	C	Fourth Event:	60 - TREE	Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Most Harmful Event:	60 - TREE	Number of Axles:	
License Restrictions:	F,B	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	98 - OTHER (EXPLAIN IN NARRATIVE)	Ejection:	2 - NOT EJECTED	HazMat Released?:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	02 - NONE USED	GVWR:	
Total Occupants:	1	Injury Status:	3 - SUSPECTED MINOR/NON- INCAPACITATING	Cit Chrg Code 1:	
Vehicle Year:	2002	Source of Trans:	03 - EMS GROUND	Citation Charge 1:	
Vehicle Make:	MERCURY - MERC	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Model:	SABLE LS PREMIU			Citation Charge 2:	
Vehicle Style:	4D			Cit Chrg Code 3:	
Vehicle Color:	RED - RED			Citation Charge 3:	
Vehicle Config:	01 - PASSENGER CAR			Cit Chrg Code 4:	
Vehicle Defect:	01 - NONE			Citation Charge 4:	
Vehicle Action:	98 - OTHER (EXPLAIN IN NARRATIVE)				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	0184				
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	99 - UNKNOWN				

Property Damage

Object Damaged:	BARBED WIRE FENCE	Company Owner Name:	
Estimate of Damage:	\$250.00	City:	WESTFIELD
Owner's Name - Last:	KNAPP	State:	IA
First:	MATTHEW	Zip Code:	51062
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	02 - SHOULDER	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	2 - DUSK	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

**** ReExam Reason: SUBJECT WS VERY CONFUSED, HAD BEEN THE SUBJECT OF AN ATTEMPT TO LOCATE DUE TO MEMORY ISSUES.

ON 5/31/17 AT 1839 THE SIOUX COUNTY SHERIFF'S OFFICE PUT OUT AN ATTEMPT TO LOCATE AT THIS VEHICLE AND DRIVER.

Narrative

The vehicle had been south bound on Hwy 12 near the intersection with 280th st. Somewhere south of 280th st the vehicle left the roadway and entered a field. The vehicle went through the same fence in this field in several locations causing damage to the fence and the vehicle. The vehicle then went over a field drive and ultimately struck a tree where it came to rest.

Diagram

