

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17007402	Report to All Drivers: NO	At Intersection with: "N/A"
Date of Acc: 07/11/17	Legal Intervention: NO	Div HWay Trvl Dir: "N/A"
Time of Acc: 06:05 Hrs.	Private Property: NO	Distance 1: "N/A"
Name of Agency: PLYMOUTH COUNTY SHERIFF'S OFF	County: PLYMOUTH - 75	Direction 1: "N/A"
Officer: TEBRINK JEFF	Acc Loc City:	Distance 2: "N/A"
Badge #: 75-3	Acc Dir From City: "N/A"	Direction 2: "N/A"
Report Date: 07/11/2017	Closest City: "N/A"	X-Coordinate: 00241526
Officer Notified: 06:09 Hrs.	Miles From City: "N/A"	Y-Coordinate: 04753994
Officer Arrived: 06:17 Hrs.	Road, Street, HWay: "N/A"	Location Literal: C012/110TH ST MEASURING
Scene Investigated: YES	Definable Location: "N/A"	Description: 2632 FEET EAST FROM US 75 AND C012/110TH ST
	Milepost Number: "N/A"	

Unit 001

Driver Name - Last: MULLINIX	Bus Use:	Transported to:
First: DONALD		
Middle: LEE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: AKRON		
State: IA	Traffic Controls:	Special Veh Func:
Zip: 51001		
Suffix:	Point of Init Impact:	Emergency Status:
Gender: Male		
Age: 47	Most Damaged Area:	Cont. Circum., Drvr:
CDL: NO		
License State: IA	Undrriid/Ovrid:	
License Class: C	Rpr/Rplc Cost: \$2,000.00	
License Endorsmnt: NONE	Ext of Damage:	
License Restrictions: B	First Event:	Carrier Name:
Speed Limit:		Carrier Address:
Seating Position:	Second Event:	Carrier City:
		Carrier State:
Driver Condition:	Third Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE	Fourth Event:	
Total Occupants: 01		Number of Axles:
Vehicle Year: 2011	Most Harmful Event:	HazMat Involvement:
Vehicle Make: CHEVROLET - CHEV		HazMat Placard:
Vehicle Model: AVEO LS/LT	Abg Switch Stat:	Placard #:
Vehicle Style: 4D	Abg Deploy:	HazMat Released?:
Vehicle Color: SILVER - SIL		Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Trapped:	GVWR:
Vehicle Defect:	Ejection:	Cit Chrg Code 1:
	Ejection Path:	Citation Charge 1:
Vehicle Action:	Occpnt Protect:	
		Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Injury Status:	Citation Charge 2:
		Cit Chrg Code 3:
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
Initial Trvl Dir:	Died at Scene: 01 - NOT APPLICABLE	
Vision Obscured:		Cit Chrg Code 4:
		Citation Charge 4:

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
	Type of Road Junc/Feat:
Surface Conditions:	
	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 31 - ANIMAL
Workers Present:	

Narrative

Vehicle #1 was traveling east on C-12. A deer came out of the south ditch and crossed in front of vehicle #1 where the two collided.

