

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-012785	Report to All Drivers: No	At Intersection with:
Date of Acc: 11/20/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 19:54 Hrs.	Private Property: No	Distance 1:
Name of Agency: Plymouth County Sheriff's Off	County: Plymouth - 75	Direction 1:
Officer: LEUSINK AARON	Acc Loc City:	Distance 2:
Badge #: 75-7	Acc Dir From City:	Direction 2:
Report Date: 11/20/2017	Closest City:	X-Coordinate: 00251696
Officer Notified: 19:54 Hrs.	Miles From City:	Y-Coordinate: 04743978
Officer Arrived: 20:05 Hrs.	Road, Street, HWay:	Location Literal: STATE 3/IOWA 3 AND PIONEER AVE
Scene Investigated: Yes	Definable Location:	Description: AVE
	Milepost Number:	

Unit 001

Driver Name - Last: WINTER	Bus Use:	Transported to:
First: MICHELLE		
Middle: LYNNE	Drvr Distractions: 02 - Not distracted	Transported by:
City: REMSEN		
State: IA	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
Zip: 51050-0000		
Suffix:	Point of Init 12 - Front Middle	Emergency Status: 01 - Not applicable
Gender: Female	Impact:	
Age: 47	Most Damaged 12 - Front Middle	Cont. Circum., Drvr: 88 - No improper action
CDL: No	Area:	
License State: IA	Undrld/Ovrld: 1 - None	
License Class: C	Rpr/Rplc Cost: \$3,500.00	Carrier Name:
License Endorsmnt:	Ext of Damage: 4 - Disabling damage	Carrier Address:
License Restrictions: B	First Event: 31 - Animal	Carrier City:
Speed Limit: 55		Carrier State:
Seating Position: 01 - 1st row: left side/motorcycle driver	Second Event:	Carrier Zip:
Driver Condition: 01 - Apparently normal		Cargo Body Type: 01 - Not applicable
Alcohol Test Given: NO	Third Event:	
Drug Test Given: 1 - None		
Total Occupants: 1	Fourth Event:	Number of Axles:
Vehicle Year: 2014		HazMat Involvement:
Vehicle Make: Dodge - DODG	Most Harmful 31 - Animal	HazMat Placard:
Vehicle Model: DAR	Event:	Placard #:
Vehicle Style: 4D	Abg Switch Stat:	HazMat Released?:
Vehicle Color: BLUE - BLU	Abg Deploy: 03 - Not deployed	Converter Dolly:
Vehicle Config: 01 - Passenger car		GVWR:
Vehicle Defect: 01 - None	Trapped: 1 - Not trapped/applicable	Cit Chrg Code 1:
Vehicle Action: 01 - Movement essentially straight	Ejection: 2 - Not ejected	Citation Charge 1:
Tow: 2 - Disabled - privately arranged	Ejection Path: 01 - Not ejected/not applicable	Cit Chrg Code 2:
	Occpnt Protect: 03 - Shoulder and lap belt used	Citation Charge 2:
Tow #:		
Initial Trvl Dir: 02 - East	Injury Status: 5 - Uninjured	Cit Chrg Code 3:
Vision Obscured: 01 - Not obscured		Citation Charge 3:
	Source of Trans: 01 - Not Transported	Cit Chrg Code 4:
	Died at Scene: 01 - Not applicable	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - On roadway	Roadway Characteristics
Manner of Crash/Collision: 01 - Non-collision (single vehicle)	Environment: 06 - Animal in roadway
Light Conditions: 5 - Dark, roadway not lighted	Roadway: 01 - None apparent
Weather Conditions: 01 - Clear	
Surface Conditions: 01 - Dry	Type of Road Junc/Feat: 01 - Non-junction/no special feature
Workzone Related: No	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: 31 - Animal
Workers Present:	

Narrative

VEHICLE #1 WAS TRAVELING EASTBOUND ON HWY 3 AND STRUCK A DEER IN THE ROADWAY. THE DAMAGE WAS DISABLING TO THE FRONT OF THE VEHICLE. THE OWNER MADE ARRANGEMENTS TO REMOVE THE VEHICLE BY PRIVATE PARTY. THERE WERE NO INJURIES TO THE DRIVER OF VEHICLE #1.



