

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-012967	Report to All Drivers: No	At Intersection with:
Date of Acc: 11/24/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 17:54 Hrs.	Private Property: No	Distance 1:
Name of Agency: Plymouth County Sheriff's Off	County: Plymouth - 75	Direction 1:
Officer: LEUSINK AARON	Acc Loc City:	Distance 2:
Badge #: 75-7	Acc Dir From City:	Direction 2:
Report Date: 11/24/2017	Closest City:	X-Coordinate: 00219666
Officer Notified: 17:54 Hrs.	Miles From City:	Y-Coordinate: 04735541
Officer Arrived: 18:00 Hrs.	Road, Street, HWay:	Location Literal: C044/230TH ST MEASURING
Scene Investigated: Yes	Definable Location:	Description: 1400 FEET EAST FROM
	Milepost Number:	C044/230TH ST AND FAWN AVE

Unit 001

Driver Name - Last: ANDERSON	Bus Use:	Transported to:
First: PAUL		
Middle: JAMES	Drvr Distractions: 02 - Not distracted	Transported by:
City: JEFFERSON		
State: SD	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
Zip: 57038-2027		
Suffix:	Point of Init Impact: 01 - Front Passenger Side Corner	Emergency Status: 01 - Not applicable
Gender: Male	Most Damaged Area: 01 - Front Passenger Side Corner	Cont. Circum., Drvr: 88 - No improper action
Age: 46	Undridd/Ovrid: 1 - None	
CDL: No	Rpr/Rplc Cost: \$7,500.00	
License State: SD	Ext of Damage: 4 - Disabling damage	
License Class: 1	First Event: 31 - Animal	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: 0		Carrier City:
Speed Limit: 55	Second Event:	Carrier State:
Seating Position: 01 - 1st row: left side/motorcycle driver	Third Event:	Carrier Zip:
Driver Condition: 01 - Apparently normal	Fourth Event:	Cargo Body Type: 01 - Not applicable
Alcohol Test Given: NO		
Drug Test Given: 1 - None	Most Harmful Event: 31 - Animal	Number of Axles:
Total Occupants: 2	Abg Switch Stat:	HazMat Involvement:
Vehicle Year: 2013	Abg Deploy: 03 - Not deployed	HazMat Placard:
Vehicle Make: Ford - FORD	Trapped: 1 - Not trapped/applicable	Placard #:
Vehicle Model: F150 S	Ejection: 2 - Not ejected	HazMat Released?:
Vehicle Style: PK	Ejection Path: 01 - Not ejected/not applicable	Converter Dolly:
Vehicle Color: BLUE - BLU	Occpnt Protect: 03 - Shoulder and lap belt used	GVWR:
Vehicle Config: 02 - Four-tire truck (pick-up)	Injury Status: 5 - Uninjured	Cit Chrg Code 1:
Vehicle Defect: 01 - None	Source of Trans: 01 - Not Transported	Citation Charge 1:
Vehicle Action: 01 - Movement essentially straight	Died at Scene: 01 - Not applicable	Cit Chrg Code 2:
Tow: 3 - Disabled - officer arranged		Citation Charge 2:
Tow #: 17000416		Cit Chrg Code 3:
Initial Trvl Dir: 04 - West		Citation Charge 3:
Vision Obscured: 01 - Not obscured		Cit Chrg Code 4:
		Citation Charge 4:

Property Damage 001


Object Damaged: COW	Company Owner Name:
Estimate of Damage: \$500.00	City: MERRILL
Owner's Name - Last: DIETERMAN	State: IA
First: STEVE	Zip Code: 51038
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - On roadway	Roadway Characteristics
Manner of Crash/Collision: 01 - Non-collision (single vehicle)	Environment: 06 - Animal in roadway
Light Conditions: 5 - Dark, roadway not lighted	Roadway: 01 - None apparent
Weather Conditions: 01 - Clear	Type of Road Junc/Feat: 01 - Non-junction/no special feature
Surface Conditions: 01 - Dry	
	FRA No.:
	Horizontal Alignment:
Workzone Related: No	Vertical Alignment:
Activity:	
Location:	First Harmful Evt of Crash: 31 - Animal
Type:	
Workers Present:	

Narrative

VEHICLE #1 WAS WESTBOUND ON C44 AND ENCOUNTERED 4 COWS ON THE ROADWAY. VEHICLE #1 STRUCK AND KILLED AT LEAST ONE COW. THE



VEHICLE HAD MAJOR DAMAGE TO THE FRONT OF THE VEHICLE AND WAS DISABLED. THERE WERE NO INJURIES TO THE OCCUPANTS OF VEHICLE #1. THE OWNER OF THE CATTLE IS UNKNOWN AT THIS TIME AND IS STILL UNDER INVESTIGATION.

Diagram

