

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18002925	Report to All Drivers: No	At Intersection with:
Date of Acc: 03/14/18	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 23:20 Hrs.	Private Property: No	Distance 1:
Name of Agency: Plymouth County Sheriff's Off	County: Plymouth - 75	Direction 1:
Officer: TEBRINK JEFF	Acc Loc City:	Distance 2:
Badge #: 75-3	Acc Dir From City:	Direction 2:
Report Date: 03/15/2018	Closest City:	X-Coordinate: 00240591
Officer Notified: 09:17 Hrs.	Miles From City:	Y-Coordinate: 04737896
Officer Arrived: 09:36 Hrs.	Road, Street, HWay:	Location Literal: C038/C38 MEASURING 1533
Scene Investigated: Yes	Definable Location:	Description: FEET EAST FROM C038/C38
	Milepost Number:	AND LYNX AVE

Unit 001

Driver Name - Last: STROMAN	Bus Use:	Transported to:
First: JESSICA	Drvr Distractions: 99 - Unknown	Transported by:
Middle: RENEE	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
City: KINGSLEY	Point of Init Impact: 02 - Front Passenger Side	Emergency Status: 01 - Not applicable
State: IA	Most Damaged Area: 02 - Front Passenger Side	Cont. Circum., Drvr: 99 - Unknown
Zip: 51028	Undrrid/Ovrid: 1 - None	Carrier Name:
Suffix:	Rpr/Rplc Cost: \$2,500.00	Carrier Address:
Gender: Female	Ext of Damage: 3 - Functional damage	Carrier City:
Age: 34	First Event: 01 - Ran off road, right	Carrier State:
CDL: No	Second Event: 59 - Mailbox	Carrier Zip:
License State: IA	Third Event:	Cargo Body Type: 01 - Not applicable
License Class: C	Fourth Event:	Number of Axles:
License Endorsmnt:	Most Harmful Event: 59 - Mailbox	HazMat Involvement:
License Restrictions:	Abg Switch Stat:	HazMat Placard:
Speed Limit: 55	Abg Deploy: 03 - Not deployed	Placard #:
Seating Position: 01 - 1st row: left side/motorcycle driver	Trapped: 1 - Not trapped/applicable	HazMat Released?:
Driver Condition: 01 - Apparently normal	Ejection: 2 - Not ejected	Converter Dolly:
Alcohol Test Given: NO	Ejection Path: 01 - Not ejected/not applicable	GVWR:
Drug Test Given: 1 - None	Occpnt Protect: 99 - Unknown	Cit Chrg Code 1:
Total Occupants: 01	Injury Status: 5 - Uninjured	Citation Charge 1:
Vehicle Year: 2008	Source of Trans: 01 - Not Transported	Cit Chrg Code 2:
Vehicle Make: General Motors - GMC	Died at Scene: 01 - Not applicable	Citation Charge 2:
Vehicle Model: ACADIA		Cit Chrg Code 3:
Vehicle Style: SUV		Citation Charge 3:
Vehicle Color: BLACK - BLK		Cit Chrg Code 4:
Vehicle Config: 03 - Sport utility vehicle		Citation Charge 4:
Vehicle Defect: 01 - None		
Vehicle Action: 01 - Movement essentially straight		
Tow: 1 - Driven away		
Tow #:		
Initial Trvl Dir: 04 - West		
Vision Obscured: 01 - Not obscured		

Property Damage 001

Object Damaged: MAILBOX AND POST	Company Owner Name:
Estimate of Damage: \$150.00	City: LE MARS
Owner's Name - Last: PENNE	State: IA
First: JARED	Zip Code: 51031
Middle: RAY	
Suffix:	

Property Damage 002

Object Damaged: MAILBOX AND POST	Company Owner Name:
Estimate of Damage: \$150.00	City: LE MARS
Owner's Name - Last: WENDT	State: IA
First: ADAM	Zip Code: 51031
Middle: JOSEPH	
Suffix:	

Accident Environment

First Harmful Event Loc: **02 - Shoulder**
Manner of Crash/Collision: **01 - Non-collision (single vehicle)**
Light Conditions: **5 - Dark, roadway not lighted**
Weather Conditions: **01 - Clear**

Surface Conditions: **01 - Dry**

Workzone Related: **No**
Activity:
Location:
Type:
Workers Present:

Roadway Characteristics

Environment: **99 - Unknown**
Roadway: **01 - None apparent**
Type of Road Junc/Feat: **01 - Non-junction/no special feature**
FRA No.:
Horizontal Alignment:
Vertical Alignment:

First Harmful Evt of Crash: **59 - Mailbox**

Narrative

Unit #1 was traveling west on C-38. Driver #1 stated that she swerved to the north to miss a deer and struck the two mailboxes. Unit #1 then continued on and reported the accident the next day.

Diagram



