

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>18005510</b>	Report to All Drivers: <b>No</b>	At Intersection with:
Date of Acc: <b>05/10/18</b>	Legal Intervention: <b>No</b>	Div HWay Trvl Dir:
Time of Acc: <b>23:55 Hrs.</b>	Private Property: <b>No</b>	Distance 1:
Name of Agency: <b>Plymouth County Sheriff's Off</b>	County: <b>Plymouth - 75</b>	Direction 1:
Officer: <b>LT JEFF TEBRINK</b>	Acc Loc City:	Distance 2:
Badge #: <b>75-3</b>	Acc Dir From City:	Direction 2:
Report Date: <b>05/11/2018</b>	Closest City:	X-Coordinate: <b>00230533</b>
Officer Notified: <b>23:56 Hrs.</b>	Miles From City:	Y-Coordinate: <b>04726672</b>
Officer Arrived: <b>00:12 Hrs.</b>	Road, Street, HWay:	Location Literal: <b>US 75 MEASURING 1402 FEET</b>
Scene Investigated: <b>Yes</b>	Definable Location:	Description: <b>SOUTH FROM WREN RD AND</b>
	Milepost Number:	<b>US 75</b>

**Unit 001**

Driver Name - Last: <b>COWLEY</b>	Bus Use:	Transported to:
First: <b>JASON</b>		
Middle: <b>ANDREW</b>	Drvr Distractions: <b>02 - Not distracted</b>	Transported by:
City: <b>SIOUX CITY</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - No controls present</b>	Special Veh Func: <b>01 - No special function</b>
Zip: <b>51104</b>		
Suffix:	Point of Init <b>12 - Front Middle</b>	Emergency Status: <b>01 - Not applicable</b>
Gender: <b>Male</b>	Impact:	
Age: <b>38</b>	Most Damaged <b>14 - Undercarriage</b>	Cont. Circum., Drvr: <b>88 - No improper action</b>
CDL: <b>No</b>	Area:	
License State: <b>IA</b>	Undrrid/Ovrid: <b>1 - None</b>	
License Class: <b>C</b>	Rpr/Rplc Cost: <b>\$3,000.00</b>	
License Endorsmnt:	Ext of Damage: <b>4 - Disabling damage</b>	
License Restrictions:	First Event: <b>31 - Animal</b>	Carrier Name:
Speed Limit: <b>65</b>		Carrier Address:
Seating Position: <b>01 - 1st row: left side/motorcycle driver</b>	Second Event:	Carrier City:
Driver Condition: <b>01 - Apparently normal</b>		Carrier State:
Alcohol Test Given: <b>NO</b>	Third Event:	Carrier Zip:
Drug Test Given: <b>1 - None</b>		Cargo Body Type: <b>01 - Not applicable</b>
Total Occupants: <b>01</b>	Fourth Event:	
Vehicle Year: <b>2016</b>		Number of Axles:
Vehicle Make: <b>Kia - KIA</b>	Most Harmful <b>31 - Animal</b>	HazMat Involvement:
Vehicle Model: <b>SORENTO LX</b>	Event:	HazMat Placard:
Vehicle Style: <b>SUV</b>	Abg Switch Stat:	Placard #:
Vehicle Color: <b>GRAY - GRY</b>	Abg Deploy: <b>03 - Not deployed</b>	HazMat Released?:
Vehicle Config: <b>03 - Sport utility vehicle</b>		Converter Dolly:
Vehicle Defect: <b>01 - None</b>	Trapped: <b>1 - Not trapped/applicable</b>	GVWR:
Vehicle Action: <b>01 - Movement essentially straight</b>	Ejection: <b>2 - Not ejected</b>	Cit Chrg Code 1:
Tow: <b>2 - Disabled - privately arranged</b>	Ejection Path: <b>01 - Not ejected/not applicable</b>	Citation Charge 1:
Tow #:	Occpnt Protect: <b>03 - Shoulder and lap belt used</b>	Cit Chrg Code 2:
Initial Trvl Dir: <b>03 - South</b>	Injury Status: <b>5 - Uninjured</b>	Citation Charge 2:
Vision Obscured: <b>01 - Not obscured</b>		Cit Chrg Code 3:
	Source of Trans: <b>01 - Not Transported</b>	Citation Charge 3:
	Died at Scene: <b>01 - Not applicable</b>	Cit Chrg Code 4:
		Citation Charge 4:

**Property Damage 001**

Object Damaged: <b>250LB HOG</b>	Company Owner Name: <b>UNKNOWN</b>
Estimate of Damage: <b>\$165.00</b>	City:
Owner's Name - Last: <b>UNKNOWN</b>	State:
First:	Zip Code:
Middle:	
Suffix:	

**Accident Environment**

First Harmful Event Loc: <b>01 - On roadway</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>01 - Non-collision (single vehicle)</b>	Environment: <b>06 - Animal in roadway</b>
Light Conditions: <b>5 - Dark, roadway not lighted</b>	Roadway: <b>01 - None apparent</b>
Weather Conditions: <b>02 - Cloudy</b>	Type of Road Junc/Feat: <b>01 - Non-junction/no special feature</b>
Surface Conditions: <b>01 - Dry</b>	
	FRA No.:
Workzone Related: <b>No</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - Animal</b>
Type:	
Workers Present:	

**Narrative**

Vehicle #1 was traveling south on Highway 75. Vehicle #1 encountered a hog in the southbound lane of traffic and was unable to avoid collision with the hog. vehicle #1



continued traveling south until it lost power and pulled over onto the shoulder to report the accident.

### Diagram

---

