

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-005746	Report to All Drivers: No	At Intersection with:
Date of Acc: 05/16/18	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 22:00 Hrs.	Private Property: No	Distance 1:
Name of Agency: Plymouth County Sheriff's Off	County: Plymouth - 75	Direction 1:
Officer: LEUSINK AARON	Acc Loc City:	Distance 2:
Badge #: 75-7	Acc Dir From City:	Direction 2:
Report Date: 05/16/2018	Closest City:	X-Coordinate: 00223607
Officer Notified: 21:46 Hrs.	Miles From City:	Y-Coordinate: 04725302
Officer Arrived: 21:51 Hrs.	Road, Street, HWay:	Location Literal: K022/K22 MEASURING 1308
Scene Investigated: Yes	Definable Location:	Description: FEET SOUTH FROM C060/C60 AND K022/K22
	Milepost Number:	

Unit 001

Driver Name - Last: BOSCH	Bus Use:	Transported to:
First: HERIZON		
Middle: LYNN	Drvr Distractions: 02 - Not distracted	Transported by:
City: VALLEY SPRINGS		
State: SD	Traffic Controls:	Special Veh Func:
Zip: 57068-9364		
Suffix:	Point of Init Impact:	Emergency Status:
Gender: Female		
Age: 16	Most Damaged Area:	Cont. Circum., Drvr: 88 - No improper action
CDL: No		
License State: SD	Undrrid/Ovrid:	
License Class: 1	Rpr/Rplc Cost: \$1,500.00	
License Endorsmnt:	Ext of Damage:	
License Restrictions: BR	First Event:	Carrier Name:
Speed Limit:		Carrier Address:
Seating Position:	Second Event:	Carrier City:
		Carrier State:
Driver Condition:	Third Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - Not applicable
Drug Test Given: 1 - None	Fourth Event:	
Total Occupants: 1		Number of Axles:
Vehicle Year: 2002	Most Harmful Event:	HazMat Involvement:
Vehicle Make: Oldsmobile - OLDS		HazMat Placard:
Vehicle Model: BRAVAD	Abg Switch Stat:	Placard #:
Vehicle Style: UT	Abg Deploy:	HazMat Released?:
Vehicle Color: BLACK - BLK		Converter Dolly:
Vehicle Config: 03 - Sport utility vehicle	Trapped:	GVWR:
Vehicle Defect:	Ejection:	Cit Chrg Code 1:
Vehicle Action:	Ejection Path:	Citation Charge 1:
Tow: 1 - Driven away	Occpnt Protect:	Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir:	Injury Status:	Cit Chrg Code 3:
Vision Obscured:		Citation Charge 3:
	Source of Trans: 01 - Not Transported	Cit Chrg Code 4:
	Died at Scene: 01 - Not applicable	Citation Charge 4:

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
	Type of Road Junc/Feat:
Surface Conditions:	
	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 31 - Animal
Workers Present:	

Narrative

UNIT #1 WAS TRAVELING NORTHBOUND ON K22 AND STRUCK A DEER THAT WAS IN THE ROADWAY. DAMAGE WAS CAUSED TO THE FRONT AND DRIVER'S FRONT OF THE VEHICLE. THE VEHICLE WAS DRIVEN AWAY FROM THE SCENE. THERE WERE NO INJURIES AS A RESULT OF THE ACCIDENT.

