

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>18-005890</b>	Report to All Drivers: <b>Yes</b>	At Intersection with:
Date of Acc: <b>05/20/18</b>	Legal Intervention: <b>No</b>	Div HWay Trvl Dir:
Time of Acc: <b>05:15 Hrs.</b>	Private Property: <b>No</b>	Distance 1:
Name of Agency: <b>Plymouth County Sheriff's Off</b>	County: <b>Plymouth - 75</b>	Direction 1:
Officer: <b>STRUVE MATT</b>	Acc Loc City:	Distance 2:
Badge #: <b>75-9</b>	Acc Dir From City:	Direction 2:
Report Date: <b>05/20/2018</b>	Closest City:	X-Coordinate: <b>00247734</b>
Officer Notified: <b>05:29 Hrs.</b>	Miles From City:	Y-Coordinate: <b>04753830</b>
Officer Arrived: <b>05:37 Hrs.</b>	Road, Street, HWay:	Location Literal: <b>110TH ST AND C012/110TH ST</b>
Scene Investigated: <b>Yes</b>	Definable Location:	Description: <b>AND STATE 60/IOWA 60</b>
	Milepost Number:	<b>MEASURING 1677 FEET NORTH</b>
		<b>FROM STATE 60/IOWA 60</b>

**Unit 001**

Driver Name - Last: <b>HAAN</b>	Bus Use:	Transported to:
First: <b>CHANCE</b>		
Middle: <b>ADAM</b>	Drvr Distractions: <b>02 - Not distracted</b>	Transported by:
City: <b>SHELDON</b>		
State: <b>IA</b>	Traffic Controls:	Special Veh Func:
Zip: <b>51201-0000</b>		
Suffix:	Point of Init	Emergency Status:
Gender: <b>Male</b>	Impact:	
Age: <b>33</b>	Most Damaged	Cont. Circum., Drvr: <b>88 - No improper action</b>
CDL: <b>No</b>	Area:	
License State: <b>IA</b>	Undrld/Ovrid:	
License Class: <b>C</b>	Rpr/Rplc Cost: <b>\$6,000.00</b>	
License Endorsmnt:	Ext of Damage:	
License Restrictions: <b>B</b>	First Event:	Carrier Name:
Speed Limit:		Carrier Address:
Seating Position:	Second Event:	Carrier City:
Driver Condition:		Carrier State:
Alcohol Test Given: <b>NO</b>	Third Event:	Carrier Zip:
Drug Test Given: <b>1 - None</b>		Cargo Body Type: <b>01 - Not applicable</b>
Total Occupants: <b>1</b>	Fourth Event:	
Vehicle Year: <b>2009</b>		Number of Axles:
Vehicle Make: <b>Dodge - DODG</b>	Most Harmful	HazMat Involvement:
Vehicle Model: <b>R15</b>	Event:	HazMat Placard:
Vehicle Style: <b>PK</b>		Placard #:
Vehicle Color: <b>ORANGE - ONG</b>	Abg Switch Stat:	HazMat Released?:
Vehicle Config: <b>02 - Four-tire truck (pick-up)</b>	Abg Deploy:	Converter Dolly:
Vehicle Defect:		GVWR:
Vehicle Action:	Trapped:	Cit Chrg Code 1:
	Ejection:	Citation Charge 1:
Tow: <b>3 - Disabled - officer arranged</b>	Ejection Path:	Cit Chrg Code 2:
		Citation Charge 2:
Tow #: <b>221</b>	Occpnt Protect:	Cit Chrg Code 3:
Initial Trvl Dir:	Injury Status:	Citation Charge 3:
Vision Obscured:		Cit Chrg Code 4:
	Source of Trans: <b>01 - Not Transported</b>	Citation Charge 4:
	Died at Scene: <b>01 - Not applicable</b>	

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
Surface Conditions:	Type of Road Junc/Feat:
	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>31 - Animal</b>
Workers Present:	

**Narrative**

Unit 1 was northbound on Hwy 60. A deer crossed the road from the west side and unit 1 struck the deer causing disabling damage to the vehicle. Most of the damage occurred on the left side. The bumper was rubbing on the front left tire.



